Picture Butte Hospital Demolition – Alberta





Project Description:

Complete hazmat remediation, demolition, reclamation and landscape works of the former 33,000 square foot Picture Butte Hospital. Great care is taken to recycle building materials, concrete and asphalt. Scope of work included removal of asbestos, demolition of the 33,000 square foot structure and landscape works of the 44,000 square foot property.

Project Location: Picture Butte, Alberta

Method of Tender: Competitive Contract Value \$550,000 Completion Date: July 2012

Safety Statistic: 0 lost time incidents

Client Contact: Alberta Health Services

Paul Edwards 403 346-4542

DAKOTA Key Personnel: Project Manager: Benny Nugent

Safety Manager: Krista Hansford GSC, NCSO